Horn Cam Revision

Part #262000011

Notice of Revision

With ididit's ongoing improvements to our steering columns, we have redesigned our horn cam.

Please note: Some components are not required with the revised Horn Cam. Please review both diagrams which illustrate the changes in the parts.





ididit inc. 610 S. Maumee St. 49286 Tecumseh, MI • PH: 517-424-0577 • FAX: 517-424-7293 • ididitinc.com Instruction #: 8000010039 REV 12/11 (reviewed 08/15)